Job Overview

Responsibilities for Machinist/Programmer

- Read technical drawings / interpret SOLIDWORKS Part drawings and set up the machines in accordance with these blueprints.

- Be familiar with computer operations and willing to learn GIBBS programming software.

- Perform quality assurance tests / inspection to ensure products meet design specifications.

- Adjust machine cutting paths or settings to optimize production while maintaining quality.

- Consider tools required to cut materials and program machines accordingly.

- Troubleshoot and resolve problems with machines as they arise.

- Perform basic machine maintenance such as cleaning, sharpening, lubricating, and zeroing.

- Maintain work area daily to include sweeping, removal of chips, garbage, organization of tooling and other equipment, checking coolant and oil levels.

- Train new employees in how to properly operate CNC machines and programs.

Qualifications for Machinist/Programmer

- High School Degree or equivalent, 2+ year degree in CNC Machine Tool

- 2+ years of CNC Machinist on the job experience.

- Must have strong attention to detail.

- Familiarity and skill with interpreting technical drawings and blueprints.

- Understanding of conversion between standard and metric measurements.

- Skilled in troubleshooting and resolving mechanical or logistical problems that arise.

- Ability to work independently and closely follow directions is essential.

- Should have a positive and professional attitude.

- Available to work overtime as requested.

- Capable of standing for extended periods of time.

- Ability to lift 25 pounds for short periods of time.

DOC ID: R-19   **Revision:** A

PRINTED COPIES ARE FOR REFERENCE ONLY. VERIFY REVISION BEFORE USING.
Confidential: May not be reproduced, distributed, or modified without Metal Professionals approval.

Release Date: 05/08/2025   **Released By:** Samantha Schick

Page **1** of **1**